

DD-WRT
Netgear Nighthawk R6700v3
WAN port speed

Problem: When upgrading the firmware of the Netgear Nighthawk R6700v3 to the most recent release. The WAN port speed decreases. This has been tested in more than several speed test websites.

First, make note of what firmware version you're currently using. Log onto you DD-WRT and its indicated top right hand corner.

Solution: Downgrade to r42015. This file can be downloaded from dd-wrt download section. Date of 1-18-2020